WIRING DIAGRAMS

Fig. 3: Computer Engine Control (Partial) (Grid 8-11)

1994 Celsior/Lexus LS 400

For Lextreme Powertrain 2020 S. Hacienda Blvd. # D Hacienda Heights California 91745

Copyright © 1998 Mitchell Repair Information Company, LLC

Thursday, June 05, 2003 03:24PM



PDF created with FinePrint pdfFactory trial version http://www.pdffactory.com